JUNIATA SUBBASIN

Susquehanna River Basin
Subbasin Survey



Frankstown & Raystown Branches of the Juniata River

SITE CONDITIONS AND WATERSHEDS

Habitat
Water Quality
Biology

RIVER/STREAM

JUNIATA SUBBASIN

HABITAT *	WATER QUALITY *	BIOLOGY *
EXCELLENT (20)	HIGHER (8)	NONIMPAIRED (7)
SUPPORTING (15)	MIDDLE (24)	SLIGHTLY IMPAIRED (11)
PARTIALLY SUPPORTING (2)	LOWER (5)	MODERATELY IMPAIRED (16)
NON SUPPORTING (0)		SEVERELY IMPAIRED (1)
NO DATA (0)		NO DATA (2)

N

* Number in parenthesis represents total number of site condition occurrences reported on map

DISCLAIMER: Intended for Educational Display Purposes Only
SRBC (1502a) 08-30-2011