

LOWER JUNIATA RIVER & SURROUNDING WATERSHEDS

SITE CONDITIONS AND WATERSHEDS

Habitat / Water Quality / Biology

RIVER/STREAM

JUNIATA SUBBASIN

HABITAT *	WATER QUALITY *	BIOLOGY *
EXCELLENT (17)	HIGHER (9)	NONIMPAIRED (9)
SUPPORTING (11)	MIDDLE (20)	SLIGHTLY IMPAIRED (11)
PARTIALLY SUPPORTING (0)	LOWER (0)	MODERATELY IMPAIRED (7)
NON SUPPORTING (0)		SEVERELY IMPAIRED (0)
NO DATA (1)		NO DATA (2)

* Number in parenthesis represents total number of site condition occurrences reported on map

DISCLAIMER: INTENDED FOR EDUCATIONAL DISPLAY PURPOSES ONLY
SRBC (1502c) 08-30-2011