

SITE CONDITIONS AND WATERSHEDS

Habitat
Water Quality
Biology

5 0 5 Miles
1:680,000

HABITAT*
- EXCELLENT (40)
- SUPPORTING (45)
- PARTIALLY SUPPORTING (6)
- NON SUPPORTING (1)

WATER QUALITY*
- HIGHER (40)
- MIDDLE (45)
- LOWER (7)

N

BIOLOGY*
- NONIMPAIRED (31)
- SLIGHTLY IMPAIRED (37)
- MODERATELY IMPAIRED (20)
- SEVERELY IMPAIRED (4)

- RIVER/STREAM
- WATERBODY
- SUBBASIN
- SUSQUEHANNA RIVER BASIN

*Number in parenthesis represents total number of site condition occurrences reported throughout subbasin